



# SOLVAY MINERALS

June 26, 1997

Lee Gribovicz  
WDEQ-Air Quality Division  
250 Lincoln Street  
Lander, WY 82520-2848

RE: MD-282 Baghouse Model Numbers

Dear Lee:

Per our conversation, the model numbers of AQD #s 68, 53, 70, and 71 are incorrectly stated in my letter dated May 29, 1997. The actual model numbers are as follows:

Emission Point	Type
AQD #68	Mikro Pulsaire Dust Collector Model 81S-10-20
AQD #53	Mikro Pulsaire Dust Collector Model 168S-10-20
AQD #70	Mikro Pulsaire Dust Collector Model 64S-10-20
AQD #71	Mikro Pulsaire Dust Collector Model 64S-10-20

I have also noted a typographical error on page 5 of the same letter, the Gas Discharged ACFM from AQD #53 is 13,300, as referenced throughout the rest of the memo, not 113,300.

I apologize for any inconvenience these changes have made. If you have further questions, please contact me at (307) 872-6571.

Sincerely,

Dolly A. Potter  
Environmental Engineer

cc: Bernie Dailey